## Approved For Release 2002@860ETIA-RDP81B00878R000100080085-5

DPD-1464-59 Copy 2 of 6 5 March 1959

Dear Side

Reference is made to my letter dated 10 Movember 1958 (DPS-5519) to Remo-Wooldridge and your letter of 30 October 1958 regarding excessive turn-around time for repair of FOG equipment under Gontract No. A-102.

Enclosed is a copy of the Contractor's reply to referenced letter setting forth the action they have taken to correct this situation.

Sincerely,

Den

Inclosures

Copy of CMOC Doc. No. 151%5.1370 (DFD-1289-59)

25X1A

73 - Contract A-	w/cy 2 of DPD-1289-59 102 w/cy 1 of DPD-1289-59 /cy 3 of DPD-1289-59 _w/cy 4 of DPD-1289-59 .teriel w/cy 5 of DPD-1289-59	25X1A
DPD_DD/P	(5 Mar 59)	NTNO.
		IGE IN CLASS ASSIFIED

25X1A

SECRET

DOGUMENT NO.

NO CHANGE IN CLASS. P

1 TO CLASSIFIED

ELASS CHANGED TO. TS S CONTROL HE VILW DATE:

CUTH. HR TO-2

DATE: LOUIST REVIEWER: 010956

## SECRET


CMCC Doc. No. 151x5.1370 Copy / of 2 February 16, 1959

Dear Dan:

You will recall in your letter of 10 November 1958 commenting that the repair cycle for FOG equipment under Contract A-102 was growing excessive. Since that time, we have investigated all outstanding work orders and have established a In order to prevent a resatisfactory schedule with currence of this excessive time lag, we have established within the field engineering organization a group whose sole responsibility will be to receive, inspect, repair and return equipment provided us under Contract A-102.

25X1A

As you know, in the past our repair and retrofit activity has been part of our production effort and as a result schedules have sometimes been paced to our regular production activity. Placing the responsibility for repair and retrofit in field engineering, we believe, will not only shorten the turnaround time, but also will bring directly to bear on the retrofit program the accumulated experience and skill of the field engineering activity.



fills degeneral contains information all cling the national I found if the U find States wouldnit be meaning of the found in Levil, in to 18 U.S. C., Scientiff, id and 754. Its transferred or the revolution of its contents in any manner to an unauthorized person is prohibited by law.

Approved For Release 2002/08/07: CIA-RDP81B00878R600100080085-5

## SLUKET

189-5519 Copy 2 of 7

10 November 1958

The Remo-Weeldridge Corporation Los Angeles, California

Gentlemen:

Initial spares provisioning for support of all systems was based on the concept of Contractor repair.

Our attention has been called to the fact that the turnaround time for this repair cycle has been excessive for FOS under
contract No. A-102. This cycle is ordinarily a maximum of
3 months and should decrease as a program progresses. Because
of the excessive turn-around time, certain items are now in
critical supply. Attached hereto is a list of Work Orders
under which rework was to have been performed.

Please advise this office as soon as possible as to the reasons for these delays and how you propose to improve the cycle time.

Very truly yours,

	25X1A
DPS/DCI pf Distribution: Orig - The R-W Corp.  2 - A-102 3 - Dir/Mat. 4 - 5 - 6 -	Contracting Officer  25X1A
7 - Chrono	DOCUMENT NO.  RC CHANGE IN CLASS, V  I FORCH ASSIRIED  CHASS CHANGED TO: TS S  OFFICE REVIEW DATE:  ALTER 198 70.2  REVIEWER 010956